

Analysis the Occurrence of Wear on Crank Pin Bearing in Diesel Engine

Didit Sumardiyanto*, Sri Endah Susilowati

Department of Mechanical Engineering, 17 Agustus 1945 University, Jakarta, Indonesia

Abstract This research was conducted on the HANSHIN type LH36L engine which is the main engine of MV. Poertocurtis. This research was triggered by the emergence of disturbances in the form of vibrations on the machine. In connection with these conditions, it is necessary to conduct research to determine the source of the problem so that the same condition does not recur in the future. The method used in this research is to dismantle the generation of elements and measure the mass of each element needed for calculations. The data obtained in the field, assuming a maximum load of 130% of the engine output power, shows that the maximum effective power, N_e is 2 486 kW, indicated power N_i is 2 825 kW, and indicated pressure, P_i is 307 N/cm². The thrust of the piston, F_{gh} is 552 640 N, the reciprocating inertia force, F_j is 62 316 N, the total force received by the piston pin, F_{sum} , and the force received by the crank pin, F_{cr} is 616 780 N, the average plane pressure journal k_{max} is 162.5 kg/cm², and the working bearing characteristics, λ_{cr} is 58.15, which is still below the tolerance limit. So that the wear of the crank pin bearing that occurs on the main engine MV. Poertocurtis is caused by impurities in the form of combustion carbon that enter the lubricating crankcase.

Keywords Wear, Crankpin, Diesel engine, Lubrication

1. Introduction

This research was conducted due to the occurrence of vibration which is quite disturbing in the operation of the diesel engine for the main propulsion of a ship. It is feared that this condition will cause greater damage in the future. Related to these conditions, an overhaul is carried out to check the elements in the power generation mechanism. The results of the inspection show that there is wear on the surface of the crankpin bearing. The diesel engine is a piston type internal combustion engine where fuel ignition is caused by the high temperature of the combustion air in the combustion chamber which reaches 550°C due to a large compression ratio, which is between 14:1 to 25:1, which provides a final compression pressure of up to 40 bar. . Because the final combustion pressure is very high, the thrust transmitted by the piston is also large. The crankshaft is a power generating element that converts the translational motion of the piston transmitted by the connecting rod into rotational motion which is then used to rotate the other engine shafts. While the crank pin bearing is the place where the crankshaft and connecting rod are connected, so that the load it receives is very large.

The research on the causes of damage to the crank pin

bearing was carried out using theoretical basics about the distribution of forces on the power generation mechanism in a piston combustion engine.

In some studies it was reported that abnormal noises can be produced by worn crank pin bearings [9,10]. There are indications that bearing failure can be caused by poor lubrication, for example insufficient amount of lubricant so that it cannot enter the gaps of the parts to be lubricated, or also due to dirt mixed in the lubricant causing erosion of the bearing walls [11]. Bearing failure can also occur due to overload so that the lubricant layer is not able to support the received load, and another possibility is the occurrence of hot rodding. From the results of this research, it can be concluded that the cause of damage to the crank pin bearing can be drawn.

2. Specifications

Table 1. Specifications of the Engine

Description	Specification
Brand	HANSHIN
Type	LH36L in-line
Number of Cylinder	6
Cycle	4-stroke
Stroke, mm	670
Bore, mm	360
Speed, rpm	270
Power output, kW	1 912

* Corresponding author:

diditsumardiyanto4@gmail.com (Didit Sumardiyanto)

Received: Jul. 10, 2021; Accepted: Aug. 6, 2021; Published: Aug. 15, 2021

Published online at <http://journal.sapub.org/jmea>

In this research, the ship used the main propulsion Hanshin diesel engine, LH36L in-line, with general specifications as shown in Table 1.

The method used in this research is through observation and documentation by disassembling the energy-producing elements and measuring the mass and dimensions of each element needed for calculations so that it can be seen the condition of the forces acting on the engine mechanism and the magnitude of the force received by the engine. crank pin bearings. The measurement results are as shown in Table 2 below.

Table 2. Measurement results of the power-producing elements

Descriptions	Value
Mass of Piston, m_p & Connecting rod, m_{cr} , kg	186
Connecting rod length, L , m	1.34
Crankpin journal diameter, D , m	0.215
Crankpin bushing thickness, m	0.18
Lubricant pressure, kg/cm^2	3.3
Piston ring gap width, mm	0.65 - 0.8

3. Result and Discussions

The calculation is carried out based on the thrust from the piston due to receiving pressure from the combustion results in the combustion chamber, which is forwarded by the connecting rod, to be converted into torque on the crankshaft [11].

3.1. Maximum Effective Power

Effective power is the real power that can be produced from a machine to be used for various purposes. From the engine specifications, the effective power generated by the engine, N_e , is: 1 912 kW.

In this calculation, the maximum effective power is based on 130% of the engine output power, so that:

Maximum Effective Power, $N_{e,max}$,

$$N_{e,max} = 130\% \times 1\,912 \text{ kW} = 2\,486 \text{ kW}$$

3.2. Indicated Power

Indicated power, N_i , is the power generated from the combustion process in the cylinder, the values are:

$$N_i = \frac{N_{e,max}}{\eta_m}$$

$N_{e,max}$: 2 486 kW

η_m : mechanical efficiency, for a 4-stroke engine with a turbocharger ranging from [11] 0.80 to 0.88, the maximum value is taken.

Then:

$$N_i = 2\,486 \text{ kW} / 0.88 = 2\,825 \text{ kW}$$

3.3. Indicated Pressure

Indicated pressure is the pressure in the combustion chamber due to fuel combustion, the value is

$$P_i = \frac{N_i \cdot 60 \cdot 102 \cdot i}{V_d \cdot n \cdot z \cdot 10^4} \text{ kg}/\text{cm}^2$$

P_i : indicated pressure, kg/cm^2

V_d : volume of the piston stroke, m^3

D : 360 mm

L : 670 mm

$$V_d = \frac{\pi D^2 L}{4} = \frac{\pi (0.36)^2 \times 0.67}{4} = 0.0682 \text{ m}^3$$

n : 270 rpm

z : 6

i : cycle ratio, for a 4-stroke engine is 2

So:

$$P_i = \frac{2\,825 \times 60 \times 102 \times 2}{0.0682 \times 270 \times 6 \times 10^4} = 31.3 \text{ kg}/\text{cm}^2 = 307 \text{ N}/\text{cm}^2$$

3.4. The Force Distribution

Due to the pressure generated by the combustion of fuel in the combustion chamber, it produces thrust on the piston. Then the force is transmitted to the crankshaft through the connecting rod. Between the connecting rod and the crankshaft there is a bearing called the crank pin bearing which is the topic of this research. The distribution of forces on the power generating elements is as shown in Figure 1.




Figure 1. Force distribution in the power engine generating [11]

The force received by the piston crown

$$F_{gh} = P_g \cdot A$$

F_{gh} : the force the piston receives

P_{gp} : $P_{i,max}$: 307 N/cm^2

A : the cross-sectional area of the piston,

D : 0.36 m: 360 mm

Then

$$A = \frac{\pi}{4} D^2 = \frac{\pi}{4} (360)^2 = 1\,080 \text{ cm}^2$$

$$F_{gh} = F_{gp}$$

F_{gp} : the force transmitted by the piston pin to the connecting rod

$$F_{gp} = 307 \text{ N}/\text{cm}^2 \times 1\,080 \text{ cm}^2 = 552\,640 \text{ N}$$

3.5. Reciprocating Inertia Force

The basic theory to determine the value of the reciprocating inertia force is [11]:

$$F_j = -m_p \cdot a = -\frac{W}{g} a$$

F_j : Reciprocating Inertia Force

$$m_p = m_{pist} + m_{cr} : 186 \text{ kg}$$

m_p : total mass

m_{pist} : mass of piston

m_{cr} : mass of connecting rod

Piston acceleration

$$a = r \cdot \omega^2 (\cos \phi + \lambda \cos 2\phi)$$

a : Piston acceleration, m/s^2

$$\lambda = \frac{r}{L}$$

$$r : \frac{1}{2} \times \text{stroke} = \frac{0.670}{2} = 0.335 \text{ m}$$

L : length of connecting rod: 1.34 m

$$\lambda = \frac{0.335}{1.34} = \frac{1}{4}$$

Crankshaft angular speed,

$$\omega = \frac{2\pi n}{60}$$

$$n: 270 \text{ rpm}$$

So

$$\omega = \frac{2 \times \pi \times 270}{60} = 28.26 \text{ rad/s}^2$$

$$a = (r) \times \left(\frac{2\pi n}{60}\right)^2 (\cos \phi + \lambda \cos 2\phi)$$

ϕ : angle of movement of the crank

$$\phi : 0^\circ (= 360^\circ),$$

$$\lambda = \frac{1}{4}$$

So

$$\cos \phi + \lambda \cos 2\phi = 1.25$$

$$r : 0.335 \text{ m}$$

$$\omega : 28.26 \text{ rad/s}^2$$

Then:

$$a = 0.335 \times 28.26^2 \times 1.25 = 355 \text{ m/s}^2$$

So reciprocating inertia force:

$$F_j = -186 \text{ kg} \times 355 \text{ m/s}^2 = 62 \text{ 316 N}$$

Furthermore, the results of the reciprocating inertia force, F_j , calculation for various angles are presented in Table 3.

Table 3. Value of reciprocating inertia force for various angles F_j

Angle ϕ , degree	0	20	40	60	80	100	120	140	160	180
	360	340	320	300	280	260	240	220	200	180
A	1.25	1.113	0.809	0.375	-0.061	-0.408	-0.625	-0.723	-0.748	-0.75
a	335	298.3	216.8	100.5	-16.35	-109.4	-167.5	-193.8	-200.5	-201.02
F_j	62 316	55 486	40 331	18 695	-3 041	-20 340	-31 158	-36 044	-37 290	-37 390

$A: \cos \phi + \lambda \cos 2\phi$

It turns out that the maximum value occurs at a crank angle of 0° and 360° , then $F_j = 62 \text{ 316 N}$.

For further calculations used at maximum load.

3.6. The Overall Force Received by the Crankpin

The overall force received by the crankpin is equal to the force received by the crank pin bearing

$$F_{sum} = F_{gp} + F_j + (m_p \cdot g)$$

$$F_{gp}: 552 \text{ 640 N}$$

$$F_j: 62 \text{ 316 N}$$

$$m_p : 186 \text{ kg}$$

$$g : 9.81 \text{ m/s}^2$$

Then:

$$F_{sum} = 552 \text{ 640} + 62 \text{ 316} + (186 \times 9.81) = 616 \text{ 810 N}$$

$$\beta = 180 - \phi \text{ at maximum load } \phi = 0^\circ$$

The overall force received by the crankpin

$$F_{cr} = \frac{F_{sum}}{\cos \beta}$$

Then

$$F_{cr} = \frac{616 \text{ 780 N}}{\cos 180^\circ} = -616 \text{ 780 N}$$

a negative sign (-) indicates the opposite direction

The load (pressure) received by the crank pin bearings:

$$k_{max} = \frac{F_{cr}}{A}$$

$$F_{cr}: 616 \text{ 780 N}$$

A : area of resisting force,

d : 21.5 mm,

L : 180.0 mm

$$A = d \cdot L = 21.5 \times 18.0 = 387 \text{ cm}^2$$

Pressure received:

$$k_{max} = \frac{616 \text{ 780 N}}{387 \text{ cm}^2} = 1 \text{ 594 N/cm}^2 = 162.5 \text{ kg/cm}^2$$

The results show that it is within the limits for the load on the crank pin bearings [4,355].

Characteristics of Bearing Working Conditions

$$\lambda_{cr} = \frac{v \cdot n}{k_{max}}$$

$$n : 270 \text{ rpm}$$

$$v : \text{dynamic viscosity SAE 10W-50, at temperature } 60^\circ\text{C,}$$

$$v : 35 \text{ cP}$$

$$k_{max} : 162.5 \text{ kg/cm}^2$$

Then the characteristic value of the bearing working condition is:

$$\lambda_{cr} = \frac{35 \times 270}{162.5} = 58.15 \left[\frac{\text{cP} \cdot \text{rpm}}{\text{kg/cm}^2} \right]$$

The values obtained are still within the characteristics of the bearing working conditions.

Tabel 4 shows the results of the calculation of the forces on the power generating elements that occur due to the pressure received by the piston during the combustion process in the combustion chamber.

Table 4. The calculation results

Description	Value
Effective power max, $N_{e,max}$, kW	2 486
Indicated power, N_i , kW	2 825
Indicated pressure, P_i , N/cm ²	307
Thrust of piston, F_{gh} , N	552 640
Reciprocating Inertia Force, F_j , N	62 316
Total force received by piston pin, F_{sum} , N	616 810
Total Force received by Crank Pin, F_{cr} , N	616 780
Average pressure on pin journal, k_{max} , kg/cm ²	162.5
Bearing Working Characteristics, λ_{cr}	58.15

3.7. The Results of the Calculations are Obtained That

- The results of the calculation show that the damage to the crank pin bearing is not due to the magnitude of the force received by the bearing. This is evidenced by the value of the average field pressure received by the crank pin bearing, which is k_{max} : 99.4 kg/cm². This value is still within the specified standard tolerance, which is 90 to 120 kg/cm², and the characteristics of the bearing working conditions λ_{cr} : 58.15 $\left[\frac{\text{cP} \cdot \text{rpm}}{\text{kg/cm}^2} \right]$ are also below the tolerance area, which is between 100 and 250 $\left[\frac{\text{cP} \cdot \text{rpm}}{\text{kg/cm}^2} \right]$.
- From observations in the field, it was found that there were deposits of dirt in the engine lubricating tub, as shown in Figure 2, which was in the form of a hard powder like sand that came from carbon. The material turned out to be the cause of the erosion of the bearing on the crank pin.
- Figure 3 is the result of several other studies on crankpin wear which show that combustion residues, water vapor, and other foreign substances produced during the combustion process of a diesel engine are the main impurities of lubricating oil. Secondary foreign substances can cause abrasion to machine parts and play a role in creating metal foreign

substances. To prevent this wear, by removing foreign substances in the engine lubricating oil by optimizing the function of the lubricating filter.



Figure 2. The hardened powder is taken from the gap of the crank pin bearing




Figure 3. Various conditions of damage to the crankpin bearing

4. Conclusions

- The engine power output, N_e , is 1,912 kW. Base on the maximum load 130% of normal, then the maximum engine power, $N_{e,max}$, 2 486 kW.
- The estimated magnitude of the indicated power, N_i , 2 825 kW, the indicated pressure, P_i , 307 N/cm², and the thrust received by the piston, F_{gh} , 552 640 N.
- The maximum inertia forcé, received by the connecting rod bearing occurs at 0° and 360° crank angle, F_j , 62 316 N, and the total force received by the bearing, F_{cr} , 616 780 N.
- The average field pressure on the bearings, k_{max} , 162.5 kg/cm², still below the standard tolerance whose value

is 90-120 kg/cm² for low speed diesel.

5. The working condition characteristic, λ_{cr} , 58.15 $\left[\frac{cP \cdot rpm}{kg/cm^2} \right]$ it is still below the standard of tolerance, that is 100-200 $\left[\frac{cP \cdot rpm}{kg/cm^2} \right]$.
6. Low Pressure The indicator from the measurement, 18.5 kg/cm² indicates that there is a problem with the piston ring, so that compression cannot be maximized.
7. Damage that occurs to the bearing of the connecting rod is caused by carbon as a result of incomplete combustion that enters through the gaps in the piston ring. The results of the calculation of the load received by the crankpin bearing, wear is not caused by the force received, because everything is still within tolerance limits, but because of the presence of carbon powder due to incomplete combustion that enters through the piston ring gap and enters the lubricating crankcase and is mixed with lubricating oil and then enters between the crankshafts.

REFERENCES

- [1] Allan T. Kirkpatrick., 2021, Internal Combustion Engines: Applied Thermosciences, Fourth Edition, John Wiley & Sons Ltd. Published 2021 by John Wiley & Sons, pp 6-20.
- [2] Xue-qin Hou et al., (2011), "Fracture Failure Analysis of Ductile Cast Iron Crankshaft in a Vehicle Engine", J Fail. Anal. and Preven, Springer, Vol 11, No. 1, pp 10-16 <https://www.proquest.com/openview/af62b7287e8f3dc1feaae0fbb62891a5/1.pdf?pq-origsite=gscholar&cbl=326254>.
- [3] Ali Keskin et al., (2010), "Crack Analysis of a Gasoline Engine Crankshaft", Gazi University Journal of Science, Vol. 23, No.4, pp. 487-492.
- [4] Fonte, M., Infante, V., Freitas, M. and Reis, L., (2016)., "Failure Mode Analysis Of Two Diesel Engine Crankshafts", Procedia Structural Integrity 1, pp 313-318. <https://www.sciencedirect.com/science/article/pii/S2452321616000433>.
- [5] Fonte, M., Duarte, P., Reis, L., Freitas, M. and Infante, V., (2015)., "Failure Mode Analysis of Two Crankshafts of a Single Cylinder Diesel Engine", Engineering Failure Analysis, Vol. 56, No. (2015), 185-193. <https://www.sciencedirect.com/science/article/abs/pii/S1350630715000709>.
- [6] Fonte, M., Li, B., Reis, L. and Freitas, M., (2013)., "Crankshaft Failure Analysis of a Motor Vehicle", Engineering Failure Analysis, Vol. 35, pp. 147-152. <https://www.sciencedirect.com/science/article/abs/pii/S1350630713000265>.
- [7] Alfares, M., Falah, A. and Elkholy, A., (2007), "Failure Analysis of a Vehicle Engine Crankshaft", Journal of Failure Analysis and Prevention, Vol. 7, No. 1, pp. 12-17. <https://link.springer.com/article/10.1007/s11668-006-9006-0>.
- [8] Pandey, R., (2003)., "Failure of Diesel-Engine Crankshafts", Engineering Failure Analysis, Vol. 10, No. 2, pp. 165-175. <https://www.sciencedirect.com/science/article/abs/pii/S1350630702000535?via%3Dihub>.
- [9] M Senthil Kumar et al., (2014)., "Analysis of Crankpin Failure in A Single Cylinder Engine", Int. J. Mech. Eng. & Rob. Res, Vol. 3, No. 4, pp, 260-268. <http://www.ijmerr.com/uploadfile/2015/0409/20150409112033746.pdf>.
- [10] M. Senthil Kumar et al., (2014)., "A Study of Crankpin Failure in I.C. Engine", Mechanical Engineering: An International Journal (MEIJ), Vol. 1, No. 3, pp. 1-12 <https://airccse.com/meij/papers/1314meij01.pdf>.
- [11] Petrowsky, "Marine Internal Combustion Engines", Mir Publisher, Moscow.
- [12] K. Aliakbari et al, (2018)., "Analysis of the Crankshaft Failure of Wheel Loader Diesel Engine".