

Evaluation of Rainfall Induced Instability of Tumulus Mounds

Mai Sawada¹, Mamoru Mimura¹, Mitsugu Yoshimura^{2,*}

¹Department of Urban Management, Graduate School of Engineering, Kyoto University, Japan

²Soil and Rock Engineering Co. Ltd, Japan

Abstract Rainfall induced instability of a tumulus mound is one of the most serious damages to tumuli. Evaluation of water infiltration and the induced instability of tumulus mounds is an important geotechnical mission for the conservation of tumuli. This paper deals with the evaluation of rainfall infiltration into the unsaturated mound and the induced instability and damage of Kengoshizuka Tumulus. Rainfall induced failure took place in the severely embrittled surface of the mound in the rainy season of 2012. The embrittled layered structure and geotechnical properties of the mound are investigated by in-situ and laboratory tests and considered in the analytical model for the evaluation. The factor of safety in terms of slope stability is calculated using the analytically estimated degree of saturation of the mound and the experimentally obtained strength parameters of the sliding surface. The results of the evaluation quantitatively show the instability of the tumulus mound induced by rainfall.

Keywords Historical geo-relics, Slope stability, Rainfall infiltration, Seepage flow analysis

1. Introduction

Tumuli are tombs for ancient emperors and district rulers constructed in various parts of Japan from the third to the seventh centuries. Tumulus mounds usually consist of densely compacted earth mounds and have chambers for coffins inside. The structure and construction method of a tumulus are characterized by the period and region in which the tumulus was constructed. Some tumuli have cultural heritages such as burial accessories and mural paintings in the chambers. Tumuli have been conserved as historical geo-relics which provide us important historical knowledge.

Tumuli, however, have been damaged by exposure to natural environment and man-caused destruction such as weathering, earthquakes, tomb robbery, urban development, etc. This paper deals with harmful rainfall infiltration into tumulus mounds which induces slope failure. The weight of the surface layer of a tumulus mound increases, meanwhile the shear strength of the sliding surface decreases with rainfall infiltration into the mound. These instability factors induced by rainfall infiltration lead to slope failure. Water seeps deeply into the mound through the failure part and the hydrothermal environment in the chamber changes. Because of this, mural paintings in the chamber are finally damaged by fungi and insects. Evaluation of water

infiltration and the induced instability of tumulus mounds is hence an important geotechnical mission for conservation of tumuli.

Rainfall induced failure took place in the severely embrittled surface of the mound of Kengoshizuka Tumulus, in Asuka village, Takaichi country, Nara prefecture, in the rainy season of 2012 (Fig. 1). The tumulus was constructed in the seventh century and added to tentative UNESCO World Heritage lists in 2006 as a part of "Asuka-Fujiwara: Archaeological sites of Japan's Ancient Capitals and Related Properties". The present study discusses the evaluation of rainfall infiltration into the unsaturated mound and the induced instability of Kengoshizuka Tumulus. Fig. 2 shows the procedure of the evaluation.

2. The Layered Structure of the Tumulus Mound and Geotechnical Properties of the Soil Layers

The tumulus mound consists of densely compacted decomposed granite soil layers called Hanchiku. The surface of the mound, however, has been embrittled mainly because of repetitive propagation and die of plants. The investigation of the layered structure of the mound and the physical, hydraulic and mechanical properties of the soil layers is important in modelling of the tumulus mound.

Fig. 3 shows plan and cross-section views of the tumulus mound. Elastic wave exploration and portable cone penetration test are conducted on the two lines shown in Fig. 3. The results on Line1 are shown in Fig. 4. Five points

* Corresponding author:

sawada.mai.43u@st.kyoto-u.ac.jp (Mitsugu Yoshimura)

Published online at <http://journal.sapub.org/jce>

Copyright © 2014 Scientific & Academic Publishing. All Rights Reserved

named A to E shows the measuring points of portable cone penetration test. The results of elastic wave test shows that shear wave velocity changes at a depth of 50 to 100 cm from the ground surface. The shear wave velocity in the surface layer is lower than that in the underlying layer. Around at the boundary of shear wave velocity, the penetration resistance reaches 500 kN/m². The results on Line2 show the same tendency with those on Line1.

These results of in-situ tests provide the analysis model shown in Fig. 5. The tumulus mound consists of the embrittled surface layer and the underlying Hanchiku layer. The densities of the two layers are assessed by a relation between density of the mound soil and compaction energy. The former studies on the density of tumulus mounds concluded that tumulus mounds were constructed by manual labor which equivalents to the compaction energy level of 0.1 to 0.2 x E_c (Proctor's compaction energy $E_c=550\text{kJ/m}^3$) [2, 3]. Here, the embrittled surface and

underlying Hanchiku layers are assumed to have dry densities with 0.1 x E_c and 0.2 x E_c , respectively. The permeability of the embrittled surface is assumed to be higher than that of the underlying Hanchiku layer considering that plants provide cracks and voids to the surface of the mound. The soil water characteristic curves of the two layers refer to those of decomposed granite soil obtained by Takeshita *et al.* [4].

The failure is assumed to occur at the boundary of the two layers. The strength parameters of the sliding surface are evaluated by a series of direct shear test on specimens under both natural and wetter conditions and needle penetration test on the excavated surface of the tumulus mound. The details are discussed by Sawada *et al.* [5]. The experimentally obtained relation between cohesion and degree of saturation of the sliding surface is shown in Fig. 6.




Figure 1. (a) The north side of the tumulus mound, (b) The failure part, (c) The entrance of the chamber (August, 2012)




Figure 2. Procedure of the evaluation of rainfall infiltration and the induced instability of the tumulus mound




Figure 3. Plan and cross-section views of Kengoshizuka Tumulus [1]





Figure 4. The results of elastic wave exploration and portable cone penetration on Line1



	Embrittled surface	Underlying Hanchiku
Dry density (g/cm ³)	1.23	1.29
Natural water content (%)	29	
Degree of saturation (%)	65	71
Hydraulic conductivity (cm/s)	3.3×10^{-3}	3.3×10^{-4}

Figure 5. The adopted model for the evaluation




Figure 6. Experimentally obtained relation between cohesion and degree of saturation

3. Evaluation of Rainfall Infiltration into the Tumulus Mound and Slope Stability

The rainfall infiltration into the tumulus mound is evaluated by saturate-unsaturated seepage flow analysis using FEM [6]. The rainfall infiltration into the tumulus

mound is evaluated during seven days from 16th to 22nd June, 2012. The amount of rainfall during the period is shown in Fig. 10. The initial condition is adjusted to the measured water content of the tumulus mound by providing appropriate amount of prior rainfall and subsequent seepage period. Here, 3.33mm/hr x 30day-prior rainfall and subsequent 200day-seepage period are adopted.

Distributions of degree of saturation of the mound during the seven days are shown in Fig. 7. The seepage water flows along the boundary of the two layers and the degree of saturation at the boundary increases day by day. This is because the permeability of the underlying Hanchiku layer is lower than that of the embrittled surface layer. The results of seepage flow analysis and in-situ tests shown before suggest that the boundary is vulnerable to failure.




Figure 7. The distributions of degree of saturation of the tumulus mound from 16th to 22nd June, 2012

The factor of safety in terms of slope stability of the tumulus mound is given by Eq.1. Here, let H , i and c be the depth, gradient and cohesion of the sliding surface, respectively. The angle of shear resistance of the sliding surface is assumed not to contribute to the safety factor. The stability analysis area is designated in Fig. 5. The experimentally obtained relation shown in Fig.6 gives c . The degree of saturation obtained by seepage flow analysis gives the wet unit of the sliding soil massy. Fig. 8 and Fig. 9 show γ and c during the seven days, respectively. The calculated safety factors are shown in Fig. 10. The safety factor continues to decrease and goes below to 1.0 on June 21st. This result explains the rainfall induced failure occurred in 2012.

$$F_s = c / \gamma H \sin i \cos i \tag{1}$$

4. Conclusions

The evaluation of rainfall infiltration into the unsaturated mound and the induced instability of the Kengoshizuka Tumulus are discussed. The results of in-situ tests show that the density and strength of the embrittled surface layer of the tumulus mound are lower than those of the densely compacted underlying layer. Based on this, the analysis model with the layered structure of the mound is adapted to the evaluation and the physical, hydraulic and mechanical properties of the soil layers are assessed. The rainfall infiltration into the mound is estimated by seepage flow analysis. The slope stability is evaluated using the analytically estimated degree of saturation of the mound and the experimentally obtained strength parameters of the sliding surface. The results of the evaluation quantitatively show the instability of the tumulus mound induced by rainfall.




Figure 8. Degree of saturation and wet unit of the sliding soil mass




Figure 9. Degree of saturation and cohesion of the sliding surface




Figure 10. The amount of rainfall and the calculated safety factor

REFERENCES

- [1] Asuka Village Board of Education. Excavation report in Kengoshizuka Tumulus, *Research report of cultural heritage in Asuka village*. 2013, 10: pp. 18-64 (in Japanese).
- [2] M. Mimura & M. Yoshimura. Geotechnical contribution for conservation of compacted tumulus mounds, *Proc. 14th ISSMGE*. 2011.
- [3] M. Sawada, M. Mimura & M. Yoshimura. Characterization of geotechnical properties for reconstruction of archeological excavations –case study of Higashinomiya Tumulus–, *Proc. Workshop ATC 19, 18th ICSMGE*. 2013.
- [4] Y. Takeshita & I. Kohno. A method to predict hydraulic properties for unsaturated soils and its application to observed data, *Ground and Construction*. 1993, 11(1): pp.95-113 (in Japanese).
- [5] M. Sawada, M. Mimura & M. Yoshimura. Evaluation of rainfall induced instability of tumulus mounds for the conservation of tumuli based on geotechnical engineering, *J.JSND*. 2014 (in press, in Japanese).
- [6] K. Akai, Y. Ohnishi & M. Nishigaki. Finite element analysis of saturated unsaturated seepage in soil, *J. JSCE*. 1977, 264: pp. 87-96 (in Japanese).